

Field Study Photographs of Sites in Eastern North Carolina

Volume 7
Wilmington, N.C., 2001

James C. Burke



PHOTOGRAPHS OF NORTH FRONT STREET AND WATER STREET
IN DOWNTOWN WILMINGTON, NORTH CAROLINA
TAKEN ON JULY 1, 2001

by

James C. Burke, Ph.D.

COPYRIGHT © 2001



Figure 1

This is the view from the second level of the parking deck on Water Street looking southeast.



Figure 2

This is the view from the second level of the parking deck on Water Street looking east.



Figure 3

This is the view from the second level of the parking deck on Water Street looking northeast to Grace Street.



Figure 4

This is the view from the second level of the parking deck on Water Street looking northeast towards the west side of North Front Street.



Figure 5

This is the view from the second level of the parking deck on Water Street looking north towards Cape Fear Community College.



Figure 6

This is a wider view taken from the second level of the parking deck on Water Street looking north towards *The Cotton Exchange* and Cape Fear Community College.



Figure 7

These shops at *The Cotton Exchange* face Water Street.



Figure 8

This parking lot is located on the south side of *The Cotton Exchange*.



Figure 9

This photograph was taken from the north ramp of the parking deck. It shows the intersection of Grace Street and North Front Street.




Figure 10

This retaining wall is located at the Front Street side of the parking lot on the south side of *The Cotton Exchange*.



Figure 11

This photograph shows details of the same retaining wall as seen in Figure 10.




Figure 12

This metal staircase is located at the southeast end of The Cotton Exchange facing North Front Street.



Figure 13

This photograph shows details of the same retaining wall as seen in Figure 10.



Figure 14

This wall is located on the north side of *The Cotton Exchange*.



Figure 15

This retaining wall is located in the parking lot on the north side of *The Cotton Exchange*.



Figure 16

This photograph shows the layers of construction found in the wall located on the north side of *The Cotton Exchange* (See Figure 14).



Figure 17

This section of a concrete retaining wall is located at the Cape Fear Community College building on the west side of North Front Street.




Figure 18

This is the retaining wall on the southeast side of the Cape Fear Community College building on the west side of North Front Street.



Figure 19

This is the Cape Fear Community College building at the southeast corner of Walnut Street and North Front Street.



Figure 20

This photograph shows another view of the same building (*See* Figure 19).



Figure 21

This is the view looking north towards the Cape Fear Community College building at the corner of Red Cross Street and North Front Street.



Figure 22

This is the east side of the Cape Fear Community College building on the west side of North Front Street.



Figure 23

This is a view of North Front Street looking towards the intersection with Red Cross Street.



Figure 24

This is the northeast corner of the Cape Fear Community College building on the west side of North Front Street.



Figure 25

A view of the Cape Fear Community College building on the west side of North Front Street looking at the entrance.



Figure 26

A view of the Cape Fear Community College building on the west side of North Front Street looking southwest.



Figure 27

A view looking south up North Front Street as seen from Red Cross Street.



Figure 28

This view shows the intersection of North Front Street and Walnut Street.



Figure 29

This is the southeast corner at the intersection of North Front Street and Red Cross Street.




Figure 30

This is the northwest corner at the intersection of North Front Street and Red Cross Street.



Figure 31

This is a view of the intersection of Red Cross Street and Water Street as seen from the southwest corner of the intersection of Red Cross Street and North Front Street.



Figure 32

A view of Water Street as seen from the northwest side of the intersection of Red Cross Street and North Front Street.



Figure 33

A view from the intersection of Red Cross Street and Water Street looking east towards the intersection of Red Cross Street and North Water Street.



Figure 34

This is a view of the northwest side of the rear of the Cape Fear Community College building facing Water Street.



Figure 35

This is another view of the same Cape Fear Community College building (*See* Figure 34).



Figure 36

This is another view of the same Cape Fear Community College building looking southeast (*See* Figure 34).



Figure 37

This is another view of the same Cape Fear Community College building looking southeast along Water Street (*See* Figure 34).



Figure 38

This is another view of the same Cape Fear Community College building looking south (*See* Figure 34).



Figure 39

This is the rear view of the same Cape Fear Community College building (*See Figure 34*).



Figure 40

Water Street curves to join Red Cross Street near the Wilmington Railroad Museum.



Figure 41

This is the intersection of Walnut Street and Water Street.




Figure 42

This is a closer view of the same intersection (*See* Figure 41).



Figure 43

This is another view of the same intersection (See Figure 41).



Figure 44

This is another view of the same intersection looking towards the parking deck on Water Street (See Figure 41).



Figure 45

This is a view looking east from the intersection of intersection of Walnut Street and Water Street (See Figure 41).



Figure 46

This photograph, taken from Water Street, shows the Grace Street side parking deck ramp on the right.



Figure 47

This photograph shows new construction underway near the south end of the parking deck on Water Street.



Figure 48

This is another view of the same structure near the south end of the parking deck on Water Street (See Figure 47).



Figure 49

This photograph shows ruins of stone retaining wall under the east end of the parking deck on Water Street.



Figure 50

This photograph shows stone and brick construction used in the same retaining walls (See Figure 49).



Figure 51

This is another view of the same retaining walls (*See* Figure 50).

